
Bullet Path Reconstruction

File Number: 2026-2566
Incident Date: 07/08/2026
Location: Seneca County

Report Date: Jul 10, 2026
Analyst: S/A M. Roberts



passenger roofline					
Trajectory Name	Description	Horizontal Angle	Vertical Angle	Tolerance	Attachments
B.I. 1.0	Passenger side door	82°	-13°	5.0°	
B.I. 4.0	Hood	10°	-13°	5.0°	
windshield roofline					
Trajectory Name	Description	Horizontal Angle	Vertical Angle	Tolerance	Attachments
B.I. 2.0	windshield	68°	-2°	5.0°	

Analyst Notes
vehicle was moving during shooting. Data is used only for documentation of angles.