Cyclone REGISTER 360 PLUS
Registration Report

2026-2933
Aug 3, 2026

Certified by:
Michael Rostocil #204
Crime Scene Technician
Ohio Bureau of Criminal Investigation
Office of the Ohio Attorney General Andy Wilson



Job 003

Overall Quality

Error Results for Bundle 1

Setup Count:	6
Link Count:	5

Bundle Error
0 ft 3/8 in ✓

Strength:	58 %
Overlap:	71 %
Global Bundle Error:	0 ft 0 in

Overlap 71 % ✓	Strength 58 % ✓
Cloud-to-Cloud 0 ft 3/8 in ✓	Target Error --

Max error of 0 ft 9/16 in.

Max error of 0 ft 13/16 in.

Error greater than 0 ft 13/16 in.

Link Error Results

1 Overview

Link Name	Setup 1	Setup 2	Overlap	Abs. Mean Error
Link 1	Job 003- Setup 001	Job 003- Setup 002	71 %	**0 ft 7/16 in**
Link 2	Job 003- Setup 002	Job 003- Setup 003	63 %	**0 ft 3/8 in**
Link 3	Job 003- Setup 003	Job 003- Setup 004	66 %	**0 ft 1/4 in**
Link 4	Job 003- Setup 004	Job 003- Setup 005	78 %	**0 ft 3/8 in**
Link 5	Job 003- Setup 005	Job 003- Setup 006	76 %	**0 ft 3/8 in**

2 Details

Link Name	Setup 1	Setup 2	Overlap	Abs. Mean Error
Link 1	Job 003- Setup 001	Job 003- Setup 002	71 %	**0 ft 7/16 in**
		Cloud to Cloud		**0 ft 7/16 in**
		Target	Mean Target Error:	**--**

Link Name	Setup 1	Setup 2	Overlap	Abs. Mean Error
Link 2	Job 003- Setup 002	Job 003- Setup 003	63 %	**0 ft 3/8 in**
		Cloud to Cloud		**0 ft 3/8 in**
		Target	Mean Target Error:	**--**

Link Name	Setup 1	Setup 2	Overlap	Abs. Mean Error
Link 3	Job 003- Setup 003	Job 003- Setup 004	66 %	**0 ft 1/4 in**
		Cloud to Cloud		**0 ft 1/4 in**
		Target	Mean Target Error:	**--**

Link Name	Setup 1	Setup 2	Overlap	Abs. Mean Error
Link 4	Job 003- Setup 004	Job 003- Setup 005	78 %	**0 ft 3/8 in**
		Cloud to Cloud		**0 ft 3/8 in**
		Target	Mean Target Error:	**--**

Link Name	Setup 1	Setup 2	Overlap	Abs. Mean Error
Link 5	Job 003- Setup 005	Job 003- Setup 006	76 %	**0 ft 3/8 in**
		Cloud to Cloud		**0 ft 3/8 in**
		Target	Mean Target Error:	**--**

Graphics



5 Feet NIST Pole 2986879.png



15 Feet NIST Pole 2986879.png